

# SUPERCAP TRANSMITTER

Operator Safety for Inactive Loops!



F16LSC, F16LSCN

## LOOP-POWERED DIGITAL PRESSURE GAUGE

*...with Super Capacitor Backup Power!*



- Display Pressure Readings if Loop is Inactive
  - Self-Recharging when Loop Power is ON
    - Recharges Fully in 2 Hours
- Maintains Charge for Months when Not in Use




### User Can Operate Gauge with Loop Power Off:

- For up to 40 minutes
- @ 15-second intervals -or- Continuous



Suggested Applications



By Mikalantis - Wikimedia Commons



Photo by Glen Dillon



### Standard Features

- ▶ **"Loop Active" LED**
- ▶ **User-Selectable Engineering Units**
- ▶ **Scalable 4-20mADC Analog Output**
- ▶ **Analog Output Test Button**
- ▶ **Zero Tare Function**
- ▶ **0.25% Accuracy**  
(0.1% avail. on most ranges)

800-942-0315  
sales@api-usa.com

[www.cecomp.com](http://www.cecomp.com)